



**2006 Dassault Falcon 900EX EASy II N317ML S/N 158**

# Dassault Falcon 900EX EASy II S/N 158

## HIGHLIGHTS

Honeywell Primus EPIC, EASy II 4<sup>th</sup> Certification

3C Inspection Scheduled April 8, 2024

13 Passenger Executive Interior

FANS 1A+ - CPDLC – ADS-B – TCAS II Change 7.1

Gogo Biz AVANCE L5 High Speed Internet Wi-Fi

Engines & APU Enrolled on Honeywell MSP Gold

Collins Avionics Service Program (CASP)

TIA Aviation Grade Microwave & TIA Coffee Maker

Dry Bay Modification Complied With

88 Parameter Flight Data Recorder

On FAR Part 135

Auto Throttles

CAMP Maintenance Tracking

## AIRFRAME

TOTAL TIME 6,752.5 Hours

LANDINGS 4,144

## ENGINES

Honeywell TFE 731-60-1C

	Engine #1	Engine #2	Engine #3
Serial Number	P112603	P112604	P112605
Total Time Since New	6,288.9	6,592.7	6,542.8
Cycles Since New	3,821	4,056	4,020

Engines Enrolled on Honeywell MSP Gold

## AUXILIARY POWER UNIT

Honeywell GTCP36-150 (F)

Serial Number P-487

Total Time 3,018 Hours

APU Enrolled on Honeywell MSP Gold



# Dassault Falcon 900EX EASy II S/N 158

## AVIONICS

Honeywell Primus EPIC, EASy II 4<sup>th</sup> Certification

Honeywell Autopilot System with Auto Throttles

Triple Honeywell Flight Management System

Honeywell AV-900 Audio Panel's W/3<sup>rd</sup> Panel

Honeywell EASy II CMF with VHF & Satellite AFIS Capability

Honeywell Primus 880 Weather Radar

Dual Honeywell DM-855 Distance Measuring Equipment

Dual Collins HF 9034A High Frequency Transceivers

Dual Honeywell XS-858B Transponders

Triple Honeywell Inertial Reference System

Honeywell SSFDR (88 Parameters) Flight Data Recorder

Emergency Locator Transmitter 406 MHZ ELT

Honeywell EASy EGPWS with Windshear Alert

Honeywell EASy II with four EFIS Displays

Dual Honeywell Track Ball Controllers

Triple Honeywell Communication Transceivers

Honeywell AA-300 with Optional Second Radio Altimeter System

Honeywell RT-951 TCAS 2000 with Change 7.1

Honeywell LSZ-860 Lightning Detection System

Dual Honeywell DF-855 Automatic Direction Finder

Honeywell SELCAL

Dual Honeywell NV-875B Navigation Receivers

Dual Honeywell GPS-90X Global Positioning System

Honeywell SSCVR Cockpit Voice Recorder

Meggitt MK2 Secondary Flight Display with Lead Acid Battery

Terrain Awareness and Warning System – TAWS with RAAS



# Dassault Falcon 900EX EASy II S/N 158

## AVIONICS UPGRADES/CERTIFICATIONS/CAPABILITIES

FANS 1/A+ - CPDLC

WAAS/LPV

TCAS II Change 7.1

Synthetic Vision

RVSM

Mode S Enhanced Surveillance

TAWS

ADS-B Out (DO-260)

NAV FM Immunity

XM Graphical Weather

VHF 8.33 MHz Spacing

406 MHz ELT

Jeppesen Electronic Charts

HUD "Full Provisions"

## ADDITIONAL EQUIPMENT UPGRADES

LED Lighting – Galley/Cabin/Aft Lavatory

TIA Microwave Oven (Aviation Grade)

Convection Oven

LED Navigation/Taxi/Tail Lights

Rosen Plug-In Monitors

(8) Cabin/Lavatory 115 VAC Outlets

Dual Life Rafts

USB Outlets – (2) Flight Deck & (9) Lighted Cabin

TIA Coffee Maker (Aviation Grade)

Hot Liquid Refreshment Canister

Vertical Stabilizer Logo Lights

3<sup>rd</sup> Crew Jump Seat W/ Oxygen Mask

(2) Cockpit Rechargeable Flashlights

Cabin Seat Jet Beds - Six Brown Storage Containers



# Dassault Falcon 900EX EASy II S/N 158

## ENTERTAINMENT/CONNECTIVITY

Gogo Biz AVANCE L5 ATG-4 High Speed Internet Wi-Fi System  
AirCell AXCESS II Satcom System  
Honeywell JetMap II System  
Forward Cabin Bulkhead with Cabin Display Monitor

Audio International AV 9693 Cabin Management /PA / Chime  
Cockpit and Wireless Cabin Phone Handsets  
Miltope TP 4840 Cockpit Printer – Copilots side  
DVD/CD Player

## INTERIOR CONFIGURATION

Interior Refurbished by Duncan Aviation June 2019  
Forward Four Place Club Executive Seating  
Left Mid Cabin Four Place Conference Group Opposite Credenza  
Left Side Aft 4 Place Divan opposite Single Forward-Facing Seat  
Forward Cabin Bulkhead w/Pocket Door  
Forward Right-Side Well-Equipped Galley  
Forward Left Side Closet Opposite Galley  
Aft Lavatory with Vanity and Sink

13 Passenger Executive Interior  
Two Executive Tables and Club Seats  
Executive Dining Table at Conference Group  
Two Left Side Divan Stowable Table Mechanisms  
Upgraded Passenger Service Units  
Forward Left Side Crew Closet  
Cabin Accessible Aft Baggage Compartment

## CUSTOM PAINT

Repainted by Duncan Aviation September 2018  
Custom Blue Stripe Color  
Registration Number Custom Blue  
LH & RH Vertical Tail Custom Blue  
Clear Coat

Overall Snow White  
Starlight Silver Stripe Color  
Registration Shadow Starlight Silver  
Emergency Exit Starlight Silver



# Dassault Falcon 900EX EASy II S/N 158



Axiom Aviation, Inc. | (216) 261-8934 | Cuyahoga County Airport | Cleveland, Ohio | [www.AxiomAv.com](http://www.AxiomAv.com)

# Dassault Falcon 900EX EASy II S/N 158



# Dassault Falcon 900EX EASy II S/N 158





# Dassault Falcon 900EX EASy II S/N 158



# Dassault Falcon 900EX EASy II S/N 158



# Dassault Falcon 900EX EASy II S/N 158



# Dassault Falcon 900EX EASy II S/N 158



# Dassault Falcon 900EX EASy II S/N 158



# Dassault Falcon 900EX EASy II S/N 158



# Dassault Falcon 900EX EASy II S/N 158





ANDY TOY | [ANDY@AXIOMAV.COM](mailto:ANDY@AXIOMAV.COM)

Call (440) 227-1466 (Direct) | Axiom Office (216) 261-8934

Axiom Aviation, Inc. | Cuyahoga County Airport | Cleveland, Ohio | [www.AxiomAv.com](http://www.AxiomAv.com)

These specifications are presented as introductory information only. They do not constitute representations or warranties of any kind. Accordingly, purchaser should rely on their own inspection of this aircraft. This aircraft availability is subject to prior sale, and/or removal from the market.

